

12.67 fps 537 kbps 15%/15810k/100M bps

640X368 Sub Resolutions Sub FPS: Sub Bit Rate: Totals

640X368 Sub Resolution: Sub FPS: 12.33 fps 551 kbps 15%/15810k/100M bps Sub Bit Rate: Total:

640X368 12.33 fps 458 kbps 15%/15810k/100M bps

**#1-FRONT DOOR** 

#2-Rt.SIDE GATE 

2022/05/25 11:22:3 UID: F

Mode: Main Resolution: Main FPS: Bit Rate: Sub Resolution: Sub FPS: Sub Bit Rate:

127.0.0.1 UID: TVI Model 2560X1920 Main Resolution: 12.33 fps Main FPS: 1528 kbps Bit Rate: 640X368 Sub Resolution: 12.67 fps Sub FPS: Sub Bit Rater 454 kbps 15%/15810k/100M bps Totals

2022/05/25 11:22:34

**#3-DRIVEWAY** 

127.0.0.1 2560X1920 12.67 fps 1544 kbps 640X368 12.67 fps 460 kbps

15%/15810k/100M bps

#4-L.SIDE YARD

#7-PATIO

#5-LSIDE LOI

#8-DOCK

#6-Rear Seawall

UIDE Mode: Main Resolution: Main FPS: Bit Rates Sub Resolution: Sub FPS: Sub Bit Roter Total

2022/05/25 11:22:33

Sub FPS: Sub Bit Rate: Total:

2022/05/25 11:22:33

Main Resolutions Main FPSs

Bit Bates Sub Resolution:

UID8 ---

Moder

Sub FPS:

Total:

Sub Bit Rate:

127.0.0.1 UID: TVI Mode: 2560X1920 Main Resolution: 12.33 fps Main FPS: 1812 kbps Bit Rate: 640X368 Sub Resolution: 12.33 fps Sub FPS: Sub Bit Rate: Totals 458 kbps 15%/15810k/100M bps

127.0.0.1

2560X1920

12.67 fps

1556 kbps

640X368

12.67 fps

472 kbps

15%/15810k/100M bps

TUD

Total:


2022/05/25 11:22:34

127.0.0.1 TYT 2560X1920 12.67 fps 1568 kbps 640X368 12.33 fps 461 kbps 15%/15810k/100M bps



HPI Security Install Example of 5MP (2560x1920) (8)Cameras on an 8 Channel DVR (Asbuilt-LOC1692)





\*2022/05/25 11:36:57

ale .

N. W.

9,


#1-FRONT DOOR




















\*2022/03/31 03:57:18

#1-FRONT DOOR



#2-Rt.SIDE GA





## \*2022/03/31 03:59:21

#5-L.SIDE LOT

>

\*2022/03/31 04:01:29

at the

#6-Rear Seawall





-

## \*2022/03/31 03:57:05 1 70 -#8-DOCK